Approved Release 2000/09/14 : CIA-RDP83B00823R000800130051-0



## EMPLOYEE BULLETIN

STATINTL

HAZARDS OF THE ENERGY-AESORBING BUMPER SYSTEM

1. Federal motor vehicle standards require all 1974 and 1975 model automboiles to be equipped with energy-absorbing bumpers. Unless safety precautions are taken, these bumpers may be hazardous after an accident.

- 2. There have been several instances of serious injury to persons attempting to separate collided vehicles equipped with energy-absorbing bumpers. Some of these bumpers are spring-loaded and, if compressed by a collision, may release with extreme force at any time after impact or upon separation if locked with bumper of mother vehicles
- 3. Another hazard exists when vehicles with these bumpers are involved in accidents and catch fire. The oil in the bumper shock absorber system may explode when heated.
- 4. Because of the danger of serious injury, it is good safety practice to avoid trying to separate collided vehicles locked together by their energy-absorbing bumpers. Instead, seek qualified assistance. It also is good safety practice to use the services of an experienced automobile mechanic when repairs to an energy-absorbing bumper are needed.

	ROUTIN	G AND	RECORD	SHEET
SUBJECT: (Optional)				
EDOM				
FROM:			EXTENSION	NO.
Acting Chief, Regulations (	Control B	ranch	3796	7 February 1975
TO: (Officer designation, room number, and building)		OFFICEDIA		
•	RECEIVED	FORWARDED	OFFICER'S C	COMMENTS (Number each comment to show from who to whom. Draw a line across column after each commen
1. 25X1A				
4E58 Hgs.				Attached is a suggested
2.				draft of the Employee Bulletin on bumpers. Please let us
				have your thoughts.
3.				You might consider putting
				this out for placement on Agence
1.				bulletin boards. We have doubts that the DDA would want this
				disseminated in the usual
•				manner.
				25X1A
				p. 5. We included 1975 autombles, but are not certain iles is correct.
				P.S. We the let
			~	1975 autombiles
				and not certain
				correct.
			- court	
				off all
				after elading with 00 1000 RCS are named objet to put on welleten boards with these publishing or Employe Bulletin.
				OD POTOS POS
			_	acs we
				sured of to put
				a let
			•	n senem vona
				exten there pulliling
			a	Employed Bulletin
				e page part